Weathertzenton Assistance Program

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: WO/17017UC-0888/1

Work Order Type: Weatherization

Audit Name: 17017UC-0888

CLIENT INFORMATION

Client ID: 17017UC-0888

AGENCY INFORMATION

Agency:Upper Cumberland H R AAgency Phone:(931) 528-1127

Address: 3313 Williams Enterprise Drive Fax:

Cookeville, TN 38506 Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

POST 1978 MOBILE HOME

Measures

Measure 1 Fix	Any Other Heating Syst	em Proble	em	Componen	ts		1	nspected
	o and clean coils on currer are nasty and need cleane			not runnina r	oroperly)			
(00110-0	no hacty and hood clouds	a ana oyo	.0111 10 1	Estimated	,		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspecified	Misc Material	Each	1					
Other Detail						,		
			Measur	e Sub Total:		,	Sub Total:	
Measure 2 sol DB Comment Door w		lock set &	:	Componen			1	Inspected
DB	L	ock set &	;	Componen Estimated			Actual	inspected
DB	L	lock set &	Qty	•		Qty		Inspected
Comment Door w	L /as damaged			Estimated		Qty	Actual	
DB Comment Door w # Material / Labor	L vas damaged Description / Comment	Units	Qty	Estimated		Qty	Actual	
DB Comment Door w # Material / Labor Doors	L vas damaged Description / Comment	Units	Qty	Estimated		Qty	Actual	
DB Comment Door w # Material / Labor Doors	L vas damaged Description / Comment	Units	Qty	Estimated			Actual Unit Cost	
DB Comment Door w # Material / Labor Doors	L vas damaged Description / Comment	Units Each	Qty 1	Estimated			Actual	Total

Measure 3 Sea	l Ducts			Componen	ts		ı	Inspected
Comment DUCTS Seal/re	pair 5 duct registers with n	nastic						
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Duct sealing (setup cost)	Each	1					
Miscellaneous Supplies	Duct Sealing	Each	1					
Other Detail								
			Measure	Sub Total:			Sub Total:	
Comment IINFILT Caulk w Weathe	neral Air Sealing RATION vindows interior and exteriorstip D3 veep x 1 D3	or x 12		Componen	ts		1	Inspected
	•			Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	General air sealing (setup cost)	Each	1					
Miscellaneous Supplies	Infiltration Reduction	Each	1					
Other Detail								
			Measure	Sub Total:			Sub Total:	
Field Notes:								

Measure 5 D Comment	WH Pipe Insulation			Componen				Inspected
44		11.20		Estimated			Actual	-
# Material / Labor	•	Units 	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DWH Pipe Insulation	Each	1					
2 Labor	DWH Pipe Insulation	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
	WH Tank Insulation			Componen				Inspected
Comment				Estimated			Actual	
Comment # Material / Labor	Description / Comment	Units	Qty	•		Qty		Inspected
Comment # Material / Labor		<i>Units</i> Each	Qty	Estimated		Qty	Actual	
Comment # Material / Labor 1 Insulation	Description / Comment		_	Estimated		Qty	Actual	
Comment # Material / Labor 1 Insulation	Description / Comment DWH Tank Insulation	Each	1	Estimated		Qty	Actual	
Comment # Material / Labor 1 Insulation 2 Labor	Description / Comment DWH Tank Insulation	Each	1	Estimated		Qty	Actual	
Comment # Material / Labor 1 Insulation 2 Labor	Description / Comment DWH Tank Insulation	Each	1	Estimated		Qty	Actual	
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DWH Tank Insulation	Each Each	1 1	Estimated			Actual	

	Fix Moisture Problems Basement/CrawIspace)			Componen	ts		1	Inspected
Comment 1809	9 sq foot of moisture barrier d	lue to dan	npness	3				
				Estimated			Actual	
# Material / Labo	r Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspecified	Moisture Barrier Needed (+)	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
		Work Or	der Gra	nd Total:		Gran	d Total:	